ASSEMBLING PROCESS





Ax4	Bx4	Cx4
Dx1	Ex8	Fx1
Gx4		